

BASIC HOT TUB CARE

- Test your hot tub water weekly.
- Maintain pH between 7.2 – 7.8.
- Maintain alkalinity between 80 – 120.
- To lower pH & alkalinity, add pH Down based on hot tub size, allow to run for 24 hours and then retest. Repeat if necessary.
- To raise pH & alkalinity, add pH Up based on hot tub size, allow to run for 24 hours and then retest. Repeat if necessary.
- Once pH and alkalinity are balanced add your Frog Bromine cartridge.
- Test your bromine level after 24 hours.
- Maintain a bromine level of 1.0 – 3.0 if you do not have ozone on your hot tub.
- Check your total alkalinity monthly to ensure it is in range.
- After each use of your hot tub, add 1 capful of oxidizing shock.
- We recommend you bring in a water sample each month so we can check your water.
- If you have a calcium level that is too high, you will need to add
- Stain & Scale to prevent calcium build-up.
- We also recommend you have Defoamer on hand in case of soap in the bathing suits.

